

# Quiz: Schematic Guide for Ethernet PHYs

TI Precision Labs - Ethernet

Prepared by Cecilia Reyes

# Quiz questions

1. What percentage of tolerance is required on RBIAS?
2. Polarity of LED will change automatically depending on strap mode – True or False
3. What type of specifications should be verified when selecting the correct magnetics for a PHY?

# Quiz answers

1. What percentage of tolerance is required on RBIAS? 1%
2. Polarity of LED will change automatically depending on strap mode – True or False - TRUE
3. What type of specifications should be verified when selecting the correct magnetics for a PHY? Return loss, 1:1 turn ratio, isolation